
Subject: Re: 7Pi Build 2014

Posted by [tubemax](#) on Sun, 14 Sep 2014 09:42:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hmmm, there is also a missing coil on your crossover which you connected only with jumper wire?

Please have a look at the picture of finished crossover from Wayne, there is a extra coil being soldered for mid horn (I think 1mH)!

Max

File Attachments

1) [Pi7_Crossover.jpg](#), downloaded 347 times
