

---

Subject: Re: 7Pi Build 2014

Posted by [Wayne Parham](#) on Tue, 21 Oct 2014 12:50:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The woofer coil should be 5.0mH to 6.0mH. The span is only about a 15% difference and is within tolerance. This is especially true in first-order filters, and even more so in this case with so much overlap between sound sources. We're looking for blending between woofer and midhorn, and any value between 5.0mH and 6.0mH is fine.

---