Subject: Re: Tim's 4Pi Speaker Build Posted by Wayne Parham on Mon, 26 Jan 2015 22:05:28 GMT View Forum Message <> Reply to Message

From the looks of that response curve, I'd still say there's something wrong. I hate to say it but my guess is the 2226 cones aren't genuine JBL. I see that pretty often in reconed JBL drivers. With good parts, the region between 500Hz and 1kHz is full and doesn't droop. In fact, since directivity increases, the on-axis output at 1kHz is actually slightly higher than it is at 500Hz.

Page 1 of 1 ---- Generated from AudioRoundTable.com