
Subject: Re: 4 pi speakers + 3 pi subwoofers, pics & measurements

Posted by [vandevoordekoen](#) on Wed, 27 May 2015 21:23:52 GMT

[View Forum Message](#) <> [Reply to Message](#)

Disconnecting the tweeter is something for tomorrow or the weekend. I measured the right tweeter (still connected to the crossover) with another mic.

This is the result:

The mic that was used for this measurement isn't perfect, but compared to the measurement with the ecm8000 mic + CAL-file, the same rolloff appears...

earlier measurement with ecm8000 and CAL-file

I guess measuring the tweeter disconnected will give a better image of the sound. To be continued...

File Attachments

1) [tweeter_right_no_cal_file_other_mic.jpg](#), downloaded 6684 times
