Subject: Re: Here's the why!

Posted by TubeCraft on Wed, 19 Jan 2005 16:08:45 GMT

View Forum Message <> Reply to Message

The \$%#@& lead out diagram packed with the bleedin' transformer was wrong! So if anyone out there's using a Hammond 124E interstage go to the website and check the corrected wiring diagram! The one printed on the carton is incorrect. Transformers don't work well a completely shorted winding.