

---

Subject: 3pi crossover

Posted by [dbbarnes2](#) on Thu, 12 Jul 2018 04:13:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

on the 3pi crossover schematic where it has a L3 and jumper, What is mh required for that coil?

---