

---

Subject: Re: Definimax 4012HO - End of Life

Posted by [Symphonimind](#) on Wed, 13 May 2020 02:36:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Wayne Parham wrote on Wed, 06 May 2020 09:52 That CDX 1745 is a nice little driver. Looks like it could be considered a drop-in replacement. Honestly, I find that most compression drivers can be used and many have the same voltage sensitivity. For those that don't, a simple R1/R2 switch usually gets the SPL right.

And speaking of that, you're right that the Delta Pro driver has higher voltage sensitivity. We specify the R1/R2 values for that driver to lower the output of the compression driver accordingly.

the updates described in this thread. So any plans that don't show the R1/R2 values required for the Delta Pro driver have an older version of the schematic.

excellent choices, and it's sort of like a Ford vs. Ferrari thing. :)

Is there a new update R1/R2 values for Delta Pro 12A? Could you please send me the update? Thank you a lot.

---