Subject: Re: Fisher 500C-how hot is too hot? Posted by hurdy\_gurdyman on Wed, 07 Sep 2005 02:03:42 GMT View Forum Message <> Reply to Message

>That's good advice. If this were my receiver, I would assume even worse, and modify the output stage to insert a cathode standoff resistor on the cathode of all 4 tubes, to further decrease plate current. I suggest a big 100 ohm wirewound resistor bypassed with a 1000 uF, 25v capacitor.

Page 1 of 1 ---- Generated from AudioRoundTable.com