

---

Subject: Re: The Blob

Posted by [Wayne Parham](#) on Mon, 06 Jul 2020 16:25:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Oh, yeah, I just love those sorts of problems. Super weird ones. Even weirder than a cold solder joint - sounds like yours was a mechanical problem caused by the physical size of the solder material causing interference with another electrical conductor, squeezing it into an unwanted connection. Nice find!

---