
Subject: Re: drool-drool!!!

Posted by [PakProtector](#) on Fri, 09 Dec 2005 02:16:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

hey-Hey!!!,My Citation II manual says that same part number applies to a 3k2 a-a. I heard there were two a-a loads, and mine ratio out at 3k1. Add DCR and we're *REALLY* close to 3k2.I don't suppose you'd care to check voltage ratio's with some 60 cps from a variac, would you? I am quite curious as to the exact details of the other version. If you do decide to get into it, could you also check the U-L tap location?cheers,Douglas
