Subject: Re: Coaxial speakers

Posted by steve f on Thu, 22 Jul 2021 16:16:54 GMT

View Forum Message <> Reply to Message

I'm guessing that there tends to be some high frequency reflections off the woofer cone. There would also be some loss of woofer cone area? Would woofer movement make for a "sloppy horn loading" my words, of the high frequency boundary? I guess I'm trying to talk myself out of my project. I don't see a good plus/minus ratio compared to a two way monitor with a well designed crossover.