
Subject: Re: Wide Spread RIAA Phono Stage Inaccuracies by Manufacturers
Posted by [Strum Drum](#) on Sun, 23 Jan 2022 01:22:50 GMT

[View Forum Message](#) <> [Reply to Message](#)

What's the reason behind the inaccuracies, though? I read the article and couldn't find the reason that so many models are like this. I saw this bit, - "These errors are due in part to the perpetuation in print of incorrect formulas for the design of the RIAA equalization networks commonly employed." However, I don't understand why it was an issue in the first place. I'm not an engineer, but I just assumed there was a standard that everyone followed.
