Subject: Re: 8 years later Posted by panduro on Thu, 27 Jan 2022 12:08:03 GMT View Forum Message <> Reply to Message

My measured ohm are

-in to -2 0.60hm In+ +2 8.9 ohm +2 -2 8.8ohm

Those numbers are consistent on both boards.

Whats next?