

---

Subject: Re: 12AX7EH-GOLD

Posted by [blades976](#) on Fri, 17 Feb 2006 16:19:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have not had the tube tested and may send it in to BOI for giggles if they feel like dissecting the thing. The original tube in the amp was a Groove Tubes 12AX7 (This may not be Hartke's OEM tube as the bass head was purchased used), the first replacement was a Groove Tubes 12AX7C (Chinese Manufacture) that made the amp go berserk. So far the outcome is pointing to either a bad tube or a bad series of tubes; shame because Groove Tubes touts their QC process as being extremely stringent. If the new tube holds up for a few weeks, I'll order another as a spare. Thanks for all the advice John

---