
Subject: Re: PS Transformers

Posted by [Damir](#) on Sat, 29 Jul 2006 04:45:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

Huh, MB...you didn't pay attention - turns ratio (N_s/N_p) is equal to the voltage ratio (U_s/U_p)...you must measure both voltages (117V i 350V in our example). Be VERY carefull with those voltages - potentially lethal, better leave this over to the qualified person if you are not sure about measuring and building with HV...

<http://www.plyrics.com/lyrics/ramones/gimmegimmeshocktreatment.html>
