

---

Subject: 12 Pi v2

Posted by [Roland Gama](#) on Thu, 14 Feb 2008 15:16:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Wayne, Need some help with the 12Pi v2 construction. In the motor chamber where panel MC-9 joins panel MC-8 with the acute angle of 67-1/2 degree cut, part of the throat cut-outs on MC-8 are blocked. I believe this is meant to be so. Is there a reason for this? Please clarify this for me so I can proceed with the job. Also, I would appreciate if you could send me the 4 Pi plans. Thanks :  
Roland

---

---

Subject: Re: 12 Pi v2

Posted by [Wayne Parham](#) on Thu, 14 Feb 2008 18:12:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

MC-8 and MC-9 meet and form the apex of the throat. The cut-outs in MC-8 open the motor chamber to the throat.

---