
Subject: I couldn't help myself

Posted by [Bill Epstein](#) on Sat, 19 Jul 2008 11:23:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

Just pulled the 6.8uF cap from the horn circuit and replaced it with an Obbligto metal film 'n oil I had on hand. A pair of the same @22uF are sitting on the bench looking at me....
