Subject: I will check the cables first...I will check the cables first...I will check the cables first...

Posted by Bill Epstein on Sat, 30 Aug 2008 03:51:26 GMT

View Forum Message <> Reply to Message

I will check the cables first... I will check the cables first...I will check the cables first...I will check the cables first...Don't ask.

Subject: Don't ask?

Posted by Wayne Parham on Sun, 31 Aug 2008 07:18:35 GMT

View Forum Message <> Reply to Message

That's like starting a compelling story and stopping just before the end. You gotta let us here the rest!

Subject: Re: Don't ask?

Posted by Bill Epstein on Sun, 31 Aug 2008 11:12:34 GMT

View Forum Message <> Reply to Message

Hardly compelling; discovering a ground fault hum when first powering up Friday, I went after the known loose RCA females attached to the Faraday cage of my tonearm. 4 hours later, I can now field-strip an SME III in the dark but everything is OK except I can discern no way to tighten the crimp-on connectors to the cage. Turning to the phono IC's, I discover no continuity for the right channel neutral in about 10 seconds and fix it in 10 minutes. As others have reported, the Eichmann Bullet neutral pin is fragile and had broken right where it inserts into the plastic collar. I "glued" it back together with solder so expect it to fail again. No more Eichmanns for me.

Subject: Re: Don't ask?

Posted by Matts on Sun, 31 Aug 2008 16:03:28 GMT

View Forum Message <> Reply to Message

I thought you might have done what I did with the last pair of new speakers- I got a phone call after moving them in position, got off, and went back and turned everything on for a listen and silence. After a brief panic, I realized I had unhooked the cables from the other speakers, but hadn't connected the new ones yet...

Subject: Re: Don't ask?
Posted by Wayne Parham on Mon, 01 Sep 2008 03:41:07 GMT
View Forum Message <> Reply to Message

Yikes, I hear you. Can't stand having fragile little connectors like that.