
Subject: Pioneer RT-909

Posted by [timestar](#) on Fri, 08 Jan 2010 19:25:12 GMT

[View Forum Message](#) <> [Reply to Message](#)

I have a RT-909 with a 7.5 speed problem - way too slow...3.75 is fine, but 7.5 almost runs the same as 3.75. Help anyone?

Subject: Re: Pioneer RT-909

Posted by [Wayne Parham](#) on Fri, 08 Jan 2010 19:36:35 GMT

[View Forum Message](#) <> [Reply to Message](#)

Mine did that too. It was a two-fold problem for me: The pinch roller was gummy and needed to be replaced. Check that - it's pretty common - If the roller feels tacky to the touch, it must be replaced. However, mine also needed an adjustment. I was lucky though - I'm told that the motors are fairly common failure modes and I'm not sure you can get those anymore. Do a search here for "Pioneer" because there are lots of posts about this unit.

Subject: Re: Pioneer RT-909

Posted by [timestar](#) on Fri, 08 Jan 2010 19:59:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

Thanks, Wayne. I'll check the pinch rollers, but I think they are new. What kind of adjustment did yours need? I'm told by local repair that it is probably a problem on the DC board at a cost of \$250.

Robert

Subject: Re: Pioneer RT-909

Posted by [Wayne Parham](#) on Fri, 08 Jan 2010 20:11:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

Mine was a "speed adjustment", but since they're DC motors, it may be the same thing your shop is talking about.

Subject: Re: Pioneer RT-909

Posted by [timestar](#) on Fri, 08 Jan 2010 21:01:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

It was the belt...I just put a new one on.

Subject: Re: Pioneer RT-909

Posted by [Wayne Parham](#) on Fri, 08 Jan 2010 22:25:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

Awesome! That's a simple fix!

Subject: Re: Pioneer RT-909

Posted by [timestar](#) on Sat, 09 Jan 2010 00:18:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

Thanks for answering and trying to help me!!

Subject: Re: Pioneer RT-909

Posted by [AudioAJ](#) on Thu, 18 Feb 2010 19:27:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

timestar wrote on Fri, 08 January 2010 15:01It was the belt...I just put a new one on.

For me, whenever I've had problems with speed issues, that's usually the first place I check. Go with the easiest and cheapest fixes first.
