
Subject: no output on a yamaha rx-385 receiver
Posted by [ricky madison](#) on Tue, 18 Oct 2005 07:32:43 GMT
[View Forum Message](#) <> [Reply to Message](#)

my yamaha receiver comes on but has no output. any help will be appreciated.

Subject: Re: no output on a yamaha rx-385 receiver
Posted by [Wayne Parham](#) on Tue, 18 Oct 2005 13:23:44 GMT
[View Forum Message](#) <> [Reply to Message](#)

Sounds like it's time to take it to the shop. If you're fairly comfortable with troubleshooting, you might be able to work on it yourself. I'd look for things like internal fuses, and don't overlook the obvious like selector switches. Then check the output transistors or IC.
