Subject: no output on a yamaha rx-385 receiver Posted by ricky madison on Tue, 18 Oct 2005 07:32:43 GMT View Forum Message <> Reply to Message

my yamaha receiver comes on but has no output. any help will be appreciated.

Subject: Re: no output on a yamaha rx-385 receiver Posted by Wayne Parham on Tue, 18 Oct 2005 13:23:44 GMT

View Forum Message <> Reply to Message

Sounds like it's time to take it to the shop. If you're fairly comfortable with troubleshooting, you might be able to work on it yourself. I'd look for things like internal fuses, and don't overlook the obvious like selector switches. Then check the output transistors or IC.