
Subject: vinagery/acic smell.....

Posted by [ARTIdaho](#) on Sun, 06 Nov 2005 23:22:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

after running tuner? Int. amp for awhile. Don't see any leakage from components.....is this electrolyte from a capacitor?? Thanx much, Chuck

Subject: Re: vinagery/acic smell.....

Posted by [Wayne Parham](#) on Thu, 17 Nov 2005 00:32:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

Did you ever find any leakage? Sometimes my tube radios make a smell when they haven't been used in a while, but I think it's the tubes heating the dust and oils that have condensed on them. Sort of like the smell of the furnace first time you turn it on for the season.

Subject: Re: vinagery/acic smell.....

Posted by [ARTIdaho](#) on Wed, 25 Jan 2006 04:36:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

yup....I can handle that smell...even kinda like it! Chuck
