

---

Subject: Technics SL-BD2 Speed not steady

Posted by [Craig](#) on Fri, 09 Dec 2005 23:23:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I am trying to get an only Technics SL-BD2 working. It is a belt drive turntable. The speed strobe was way off, so I replaced the belt with a new one. Now the speed is much more steady, but every half second "hiccups" - I've read this is the "wow" of wow and flutter. Also, the strobe marking on the platter moves vertically up and down - just a bit, so I wonder if the spindle is a tiny bit off. Can I fix this turntable, throw it away, or sell it on ebay as "perfect condition" (just kidding!)

---