
Subject: 1pi port and insulation
Posted by [justphil](#) on Sat, 08 May 2021 14:41:02 GMT
[View Forum Message](#) <> [Reply to Message](#)

Good morning. I have a problem with the insulation standing up into the port area. Is it possible to fix this somehow? Thank you

Subject: Re: 1pi port and insulation
Posted by [Wayne Parham](#) on Sat, 08 May 2021 15:36:51 GMT
[View Forum Message](#) <> [Reply to Message](#)

I use R11/R13 and it doesn't overlap the port on a one Pi cabinet. It just lines the interior walls, specifically the rear, bottom and side nearest to the port. You kind of have to "tuck in" the side and bottom sheets beside the port.

Is that what is happening in your situation? Are you using sheets of fiberglass insulation or something else?

Subject: Re: 1pi port and insulation
Posted by [justphil](#) on Sat, 08 May 2021 15:57:40 GMT
[View Forum Message](#) <> [Reply to Message](#)

It is tucked in but seems really fluffy and thus sticks up into the port area. I built these forever ago and it's always been this way. Thanks for the help.

Subject: Re: 1pi port and insulation
Posted by [Wayne Parham](#) on Sat, 08 May 2021 16:27:45 GMT
[View Forum Message](#) <> [Reply to Message](#)

If it's just bulging where it meets the port, it's fine. That's to be expected.
