

---

Subject: unstable platter

Posted by [Philippe](#) on Sat, 06 Jan 2007 14:03:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Just bought a Technics SL 1210 M5G, after putting the platter on the pin, the platter is not stable.. it has a bit of movement to it. I can play records, but scratching is an issue.. did I assemble it wrong?The service center here says that all models of this are like that. Are they sending me off without doing anything> is there anything I can do?

---

Subject: Re: unstable platter

Posted by [Wayne Parham](#) on Mon, 08 Jan 2007 21:04:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Not many scratchers hang out here. This place is mostly for audiophiles. That said, I wouldn't expect much play in the platter bearing. It's basically a zero-clearance fit. The tolerance is so tight on a good turntable that there isn't even room for a film of oil. There doesn't need to be any room for heat expansion, and you don't want any chatter. So the clearance in this bearing should be extremely close.

---

Subject: Re: unstable platter

Posted by [Listens2tubes](#) on Sun, 28 Jan 2007 19:08:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You may want to email Kevin at <http://www.KABUSA.com>, he is very knowledgable with Technics tables.