

---

Subject: Pioneer RT - 707 woes (wows)

Posted by [MOGUL](#) on Fri, 03 Feb 2006 16:18:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi,I have a mint condition Pioneer RT – 707. I know one of the specs for these decks used to be wow and flutter. Wow does it have wow - almost slows to a halt at times and lots of chipmunks at either speed. FF and Rew seem to be OK although rewind tends to spill a little tape. Previous owner says he hasn't used it in a while and says "the wheels may need lubricating" but forgets how to do it. No manual. Can anyone help?Thanks,John

---

Subject: Re: Pioneer RT - 707 woes (wows)

Posted by [Wayne Parham](#) on Fri, 03 Feb 2006 20:17:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

You need a speed adjustment, and you may also need a pinch roller. It's possible you may need a motor or two. If you're comfortable working on the deck, pick up a service manual at [StereoManuals.com](#) and perform the adjustments prescribed. Pinch rollers were still available from Pioneer last time I checked, which was about two years ago. Mine had become jelly bears, so I bought a new one and a couple extras to keep on hand.

---

Subject: Re: Pioneer RT - 707 woes (wows)

Posted by [MOGUL](#) on Sat, 04 Feb 2006 17:13:45 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks Wayne. I'm looking into these things.John

---