
Subject: Dynaudio speaker Recon
Posted by [Garrett Roach](#) on Thu, 17 Apr 2008 05:42:30 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi I have a Dynaudio 17W75EXT woofer that needs to be reconed. The voice coil rubs when pressed gently in the center of the cone. Although it seems to play well when installed. It is one of the older ones. I have checked with Madisound and Meniscus Audio and neither can do the recone. Can any of you Audio gurus help me with this. Thanks, Gary

Subject: Re: Dynaudio speaker Recon
Posted by [Wayne Parham](#) on Thu, 17 Apr 2008 16:27:42 GMT
[View Forum Message](#) <> [Reply to Message](#)

Check with David Miller at Speakerworks. (918) 664-6299 or (800) 526-8879

Subject: Re: Dynaudio speaker Recon
Posted by [Garrett Roach](#) on Thu, 17 Apr 2008 17:57:19 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi Thank you very much. I'll give him a call. Regards, Gary