

---

Subject: recond Sansui 500A

Posted by [jim denton](#) on Wed, 29 Dec 2004 15:09:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

after going thur all my stuff I have picked this Sansui Reciever to work on as I know a bit about what is wrong--though that doesn't mean I know exactly what needs to be replaced to correct the problem---one of the output trannies run hot---so I know I can change the out put caps ---what else---is the question---Jim

---

---

Subject: Re: recond Sansui 500A

Posted by [Bill G](#) on Tue, 18 Jan 2005 14:20:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Jim,I just completely recapped my 500A, every electrolytic cap in the set needs to be renewed. I can guarantee that they are long since dried out. The build dates on the caps on my unit were 3rd month of 1975 so they're way out of warrantee. The 20uF multisection cap near the front of the unit on the left as you face it will not be available. Use the equivalents or greater and tuck them underneath the chassis. Digi-key is an excellent source of small quantities of those units. There are also tub tubular (paper) bypass caps (small value) that can be replaced by poly-props, make sure the working voltage meets or exceeds the originals. After recapping the sound was amazing, I highly recommend the repair.

---

---

Subject: Re: recond Sansui 500A

Posted by [Bill G](#) on Tue, 18 Jan 2005 14:22:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Jim,Also if you need service notes and schematics you can get the from AGTannenbaum out of PA. Very reasonable and excellent service.BG

---