

---

Subject: faulty reverb

Posted by [ratchet1021](#) on Tue, 09 Oct 2007 00:21:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

having trouble with the reverb on a silver face fender deluxe. have replaced the reverb unit itself, fully retubed the amp. when turning the verb up it seems to boost the sound but doesnt have any reverb to it, and when you get up to 7 it starts squeeling very loud. ive takin the tank out and put it in my twin and it seems to work. will listen to any suggestions, ideas, help advice. gotta get this thing working

---

---

Subject: Re: faulty reverb

Posted by [decoy](#) on Fri, 09 Nov 2007 19:00:54 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have the same problem with my princeton, Try changing the wires that go out of the tank they should just be AV wires. If that doesn't work try changing the in wires.

---