

---

Subject: KSN1038

Posted by [wasteh202](#) on Sat, 20 Mar 2004 20:15:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Wayne...Thanks for the advice about the KSN1038. I did take the piezo apart as you suggested. It did have alot of debris inside. Most of it seemed to be plastic bits, probably from screwing the horn together. Nonetheless it may have been contributing to the problem. I think most of the distortion I am hearing is coming from the mid/woffer. I did wrap the backside of the KSN1038's with some Rope Caulk... and I must say I believe there is a difference for the better. I will likely treat the Alpha 10 baskets with something also... I am not sure about the Rope Caulk for those. Thanks to all who resounded.

---

---

Subject: Re: KSN1038

Posted by [Wayne Parham](#) on Sun, 21 Mar 2004 03:28:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Glad you found the junk inside, and glad you got rid of it too. That didn't sound right. I'm not actually glad you found junk inside, well, you know what I mean.

---

---

Subject: Re: KSN1038

Posted by [wasteh202](#) on Sun, 21 Mar 2004 03:35:58 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes... I was really surprised how much there was... and how easy it was to do the job. Thanks again for the help Wayne, you are always SO helpful !! I would recommend to everybody that is using the KSN-1038 to open them up and dump the junk inside... I doubt that mine were far from what many others have inside them.

---

---

Subject: Re: KSN1038

Posted by [Adrian Mack](#) on Sun, 21 Mar 2004 10:26:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Was there junk inside it when you took it out of the carton that you bought it in?

---

---

Subject: Re: KSN1038

Posted by [wasteh202](#) on Sun, 21 Mar 2004 12:48:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

No! Although I never opened up the peizo out of the package to inspect them at the time. They were sealed in plastic as Wayne ships them with the wire harness and logos. I would have never suspected there was that much stuff in there. Perhaps some of the tiny bit of the saw dust was added by me ? Don't know.

---