

---

Subject: Re: Filling behind the horn of the A7/828 cabinet

Posted by [jjsvg](#) on Mon, 28 Nov 2005 16:53:40 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Such a drastic measure, this concrete idea. I found that a large tube sock, filled with rice, works excellently as a non invasive fix for the ringing. I got the idea by accidentally placing a "bed buddy" on one of the horns and noticed that it didn't ring, even when tapped. A bed buddy is one of those microwaveable things that you put on your neck to relieve muscle pain. It's cheap, works 90% and doesn't mess up the horn.

---