Subject: Damaged Wizzer Cone Posted by gfederys on Wed, 10 Jan 2007 16:46:08 GMT View Forum Message <> Reply to Message

Hi all, I need to repair a tear in a EV LS8. The tear is about an inch long, fits together tightly, and can be accessed from behind the wizzer cone. I was thinking of mixing some Tightbond with a drop of water and applying it with either a toothpick or a fine needle hypodermic along the crack. Does this sound like it'll work or does someone have a better solution? Thanx in advance for the help.

Page 1 of 1 ---- Generated from AudioRoundTable.com