
Subject: Re: Ground isolated from chassis - now it's an AM radio

Posted by [colinhester](#) on Sun, 06 Mar 2005 15:02:17 GMT

[View Forum Message](#) <> [Reply to Message](#)

I pulled the signal path apart last night and will redo it soon. I did notice that the insulation in the shielded cable I was using in the signal path had stretched in some places and was making contact with the shielded drain in more than one place. I'm going back and replace with either non-shielded solid-core Cu or stranded Ag wire.....Colin
