Subject: Cracked Turntable Cover repair
Posted by Ross Rakoff on Wed, 17 Jun 2009 02:59:08 GMT
View Forum Message <> Reply to Message

I just picked up this beautiful Luxman PD444. This is the best table I have ever owned. On the way home I think the turntable cover popped up and down and caused it to crack in the rear right corner where it fastens. Anyone know of a componay that can restor the clear plastic crack so it looks perfect?