Subject: Re: 3pi nearing completion. Posted by cookietruck on Wed, 16 Sep 2009 12:52:07 GMT View Forum Message <> Reply to Message

speakers are all glued up. snapped a pic right before i added some fiberglass to damp and glued the backs on.

the crossover pcb looks like its stressed but its not. it looks like that because i had some high density foam that i hadn't used, small strip. cut squares to stuck to the bottom side of the crossover pcb before screwing down...

Page 1 of 1 ---- Generated from AudioRoundTable.com