
Subject: Re: 7Pi Build 2014

Posted by [my0x](#) on Sun, 14 Sep 2014 00:34:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

It appears you have resistors R1b and R1d touching the trace from L1. I think they should not touch this trace and only touch at the pad below. Double check all traces against the schematic

Matt

File Attachments

1) [pi7 xover markup.jpg](#), downloaded 9509 times
