Subject: Re: Building a Home Theater & Listening Room Posted by hydrovac on Thu, 05 Feb 2015 17:42:46 GMT View Forum Message <> Reply to Message Framing work completed and AV cabinet in place.... cabling almost done except one sub signal cable. Got 20 Rock wool bags delivered yesterday. There was a leak from one point of the slab joint side.... getting the pressure grouting done today. Entry door to the theater on the left: Bags containing Rock wool slabs: AV cabinet built into the window: Ceiling panels getting ready: Insulation panels being fixed:

File Attachments

```
1) IMG_5653.jpg, downloaded 5013 times
2) IMG_5654.jpg, downloaded 5004 times
3) IMG_5655.jpg, downloaded 4991 times
4) IMG_5656.jpg, downloaded 5011 times
5) IMG_5657.jpg, downloaded 4991 times
6) IMG_5734.jpg, downloaded 5008 times
7) IMG_5735.jpg, downloaded 4962 times
8) IMG_5746.jpg, downloaded 5032 times
9) IMG_5749.jpg, downloaded 5011 times
10) IMG_5750.jpg, downloaded 5003 times
11) IMG_5753.jpg, downloaded 5019 times
```