Subject: Re: Pete's Home Theater Build
Posted by petew on Mon, 27 Apr 2026 15:42:20 GMT
View Forum Message <> Reply to Message

Look at the upper XO in the pic above. C3 is shorted to ground instead of passing through L1. I found the mistake with a bit of sleuthing and the fix was easy. Luckily I used the silicone in moderation when I assembled the crossovers.